



















































PARAMETRIC BOX CATALOGUE 2015



Box code	3D drawing	Box scheme	wave orientation	Units required
0200				3
				6
0200M				3
				4
0200S				3
				6
0201				4
				6
0201M				4
				4
0201S				4
				6




















Box code	3D drawing	Box scheme	wave orientation	Units required
0202		 BLBLK₁ B/2+K₂HB/2+K₂		4
				6
0202S		 LBLBK₁ B/2+K₂HB/2+K₂		4
				6
0203		 BLBLK₁ BHB		4
				6
0203M		 LBK₁ BHB		4
				4
0203S		 LBLBK₁ BHB		4
				6
0204		 BLBLK₁ L/2L/2B/2HB/2		6
				6

Box code	3D drawing	Box scheme	wave orientation	Units required
0204S				6
				6
0205				4
				6
0206				6
				6
0209				4
				6
0209S				4
				6
0210				6
				6





















Box code	3D drawing	Box scheme	wave orientation	Units required
0212				5
				6
0228				4
				8
0230				4
				6
0231				4
				6
0300				4
				4
0301				4
				4



Box code	3D drawing	Box scheme	wave orientation	Units required
0302				4
				4
0306	 			4
				4
0310	 			4
				6
0311				4
				6
0312	 			4
				6
0312S				4
				6



Box code	3D drawing	Box scheme	wave orientation	Units required
0313				4
				6
0314				4
				6
0314S				6
				10
0320				3
				6
0330				6
				10
0331				8
				8
















Box code	3D drawing	Box scheme	wave orientation	Units required
0331R				10
				10
0331S				4
				8
0332				8
				8
0332S				4
				8
0400				6
				6
0401				6
				6










































Box code	3D drawing	Box scheme	wave orientation	Units required
0402				6
				6
0403				6
				10
0404				2
				6
0405				2
				7
0409				4
				6
0410				4
				6




































Box code	3D drawing	Box scheme	wave orientation	Units required
0410R				4
				6
0410S				4
				6
0411				4
				6
0412				6
				6
0413				7
				6
0415				6
				6


















Box code	3D drawing	Box scheme	wave orientation	Units required
0415S				6
				6
0416				6
				6
0420				6
				8
0420S				6
				6
0421				6
				8
0426				4
				9



















Box code	3D drawing	Box scheme	wave orientation	Units required
0427				6
				8
0427S				6
				12
0428				6
				10
0441				6
				6
0442				10
				6
0442S				10
				6


















Box code	3D drawing	Box scheme	wave orientation	Units required
0443				6
				6
0444				6
				6
0454				4
				8
0454R				4
				10
0454RS				10
				12
0454S				8
				8







Box code	3D drawing	Box scheme	wave orientation	Units required
0470				6
				7
0502				2
				6
0504				2
				6
0900				2
				2
0905				2
				5
0910				6
				2

Box code	3D drawing	Box scheme	wave orientation	Units required
0914	 	 H B H B H		6
				2
0946	 	 K1 H K1 H L H K1 H B K1		2
				10
0951		 H B H		4
				2
0954		 L H L B		2
				4
P004	 	 L H H		2
				2
P004S		 L H H		2
				4

Box code	3D drawing	Box scheme	wave orientation	Units required
P005				2
				4
P005S				2
				6
P011				6
				-
P012				4
				8
P013				6
				-
P014				-
				-

Box code	3D drawing	Box scheme	wave orientation	Units required
P018				2
				12
P018R				2
				-
P030R				6
				4
P201F				5
				10
P331				10
				12
P331S				10
				12

Box code	3D drawing	Box scheme	wave orientation	Units required
P403c				6
				10
P403e				4
				10
P403f				4
				10
P403g				4
				10
P442a				8
				6
P900a				3
				2

Box code	3D drawing	Box scheme	wave orientation	Units required
P951a				6
				8
P951b				2
				8